

Vinyl Pasted On 3mm Foam Sheet

Size - 18 X 12 Inch - Each 2 No.

 UNISON PHARMACEUTICALS PVT.LTD. UNIT-III, C7,8,9 STEEL TOWN, MORAIYA, AHMEDABAD.					QC3/090/F01/02 Page No : 1 of 4
ENTRY PROCEDURE FOR SAMPLING AREA					
					
STEP-1: Enter To Personnel Air Lock STEP-2: Remove out side slipper and kept in designated place STEP-3: Take The Clean Garment From designated Location STEP-4: Wear Head Gear STEP-5: Wear Light Pista Boiler Suit					
Approved By : QA-Head					

 UNISON PHARMACEUTICALS PVT.LTD. UNIT-III, C7,8,9 STEEL TOWN, MORAIYA, AHMEDABAD.					QC3/090/F01/02 Page No : 2 of 4
ENTRY PROCEDURE FOR SAMPLING AREA					
					
STEP-6: Wear Booties STEP-7: Crossing Cross Over Bench STEP-8: Proper Hand Sanitizing STEP-9: Wear hand Gloves STEP-10: Enter to Sampling Room					
Approved By : QA-Head					

 UNISON PHARMACEUTICALS PVT.LTD. UNIT-III, C7,8,9 STEEL TOWN, MORAIYA, AHMEDABAD.				QC3/090/F01/02 Page No : 3 of 4
EXIT PROCEDURE FOR SAMPLING AREA				
				
STEP-1: Exit from sampling Room STEP-2: Remove hand gloves keep it in waste bin STEP-3: Crossing Cross Over Bench Remove Booties STEP-4: Remove Booties & keep in used garments				
Approved By : QA-Head				

 UNISON PHARMACEUTICALS PVT.LTD. UNIT-III, C7,8,9 STEEL TOWN, MORAIYA, AHMEDABAD.				QC3/090/F01/02 Page No : 4 of 4
EXIT PROCEDURE FOR SAMPLING AREA				
				
STEP-5: Remove Boiler Suit & keep in used garments STEP-6: Remove Head Gear & keep in used garments STEP-7: Wear blue slipper STEP-8: Exit from Personnel Air Lock				
Approved By : QA-Head				