

SOURCE - INSPECTION RELEASE NOTE

Particulars of project

DNV project name: _____
 DNV customer name: M/s COMPOSITE STRAP INDIA PVT. LTD.
 Supplier: M/s COMPOSITE STRAP INDIA PVT. LTD.
 Manufacturer: M/s COMPOSITE STRAP INDIA PVT. LTD.
 DNV acts on behalf of: M/s COMPOSITE STRAP INDIA PVT. LTD.
 DNV project number: _____
 DNV assignment number: _____
 DNV order/PO number: _____

Inspection details

Customer's PO number to Supplier: _____
 Supplier's reference: _____
 Additional references: INSPECTION CALL VIA EMAIL DATED 25TH JANUARY 2022
 Inspection location: M/s. COMPOSITE STRAP INDIA PVT. LTD., SURVEY NO. 2113,2122, DAMANGANGA ESTATE, PLOT NO. 23,31, KARVAD VILLAGE, VAPI, GUJARAT.
 Number of ITP items covered: AS DOCUMENTED IN IR

The following items were inspected and are released under applicable scope of work

| Sr. No. | Description of Strap | Standard Linear Breaking Load (Kg) | Observed actual Linear Breaking Load (Kg) | Standard System Breaking Load (Kg) With Buckle | Observed actual System Breaking Load (Kg) With Buckle |
|---------|--|------------------------------------|---|--|---|
| 1 | CS25PX450-F COMPOSITE STRAP X-SERIES 25MM PLATINUM | 1150 | 1240 | 2000 | 2040 |

Comments:

This release note issued on basis of report number: **DNV/PUNE/CSIPL/2022/DL/IR-01C. Rev. 00. Dated: 02.02.2022.**





Report No:
DNV/PUNE/CSIPL/2022/DL/IRN-01C
Revision No: **00**

SOURCE - INSPECTION RELEASE NOTE

Issuance of this release does not relieve the manufacturer of any of his responsibilities and/or obligations; and from complying with any and all expressed or implied specifications, or manufacturer's guarantee that the material shall perform satisfactorily under conditions of reasonable service.

Report issued on **(2022-02-02)**

DNV Performing office: **PUNE**
DNV Contracting office: **MUMBAI**

for **DNV**

(DATTATRAY LOKHANDE)
Inspector

Stamp:

