

Report No:
DNV/PUNE/CSIPL/2022/DL/IRN-01C
 Revision No:
00

SOURCE - INSPECTION RELEASE NOTE

Particulars of project

DNV project name: _____
 DNV customer name: M/s COMPOSITE STRAP INDIA PVT. LTD.
 Supplier: M/s COMPOSITE STRAP INDIA PVT. LTD.
 Manufacturer: M/s COMPOSITE STRAP INDIA PVT. LTD.
 DNV acts on behalf of: M/s COMPOSITE STRAP INDIA PVT. LTD.
 DNV project number: _____
 DNV assignment number: _____
 DNV order/PO number: _____

Inspection details

Customer's PO number to Supplier: _____
 Supplier's reference: _____
 Additional references: INSPECTION CALL VIA EMAIL DATED 25TH JANUARY 2022
 Inspection location: M/s. COMPOSITE STRAP INDIA PVT. LTD., SURVEY NO. 2113,2122, DAMANGANGA ESTATE, PLOT NO. 23,31, KARVAD VILLAGE, VAPI, GUJARAT.
 Number of ITP items covered: AS DOCUMENTED IN IR

The following items were inspected and are released under applicable scope of work

Sr. No.	Description of Strap	Standard Linear Breaking Load (Kg)	Observed actual Linear Breaking Load (Kg)	Standard System Breaking Load (Kg) With Buckle	Observed actual System Breaking Load (Kg) With Buckle
1	CS25PX450-F COMPOSITE STRAP X-SERIES 25MM PLATINUM	1150	1240	2000	2040

Comments:

This release note issued on basis of report number: **DNV/PUNE/CSIPL/2022/DL/IR-01C. Rev. 00. Dated: 02.02.2022.**





Report No:

DNV/PUNE/CSIPL/2022/DL/IRN-01C

Revision No:

00

SOURCE - INSPECTION RELEASE NOTE

Issuance of this release does not relieve the manufacturer of any of his responsibilities and/or obligations; and from complying with any and all expressed or implied specifications, or manufacturer's guarantee that the material shall perform satisfactorily under conditions of reasonable service.

Report issued on **(2022-02-02)**

DNV Performing office: **PUNE**

for **DNV**

DNV Contracting office: **MUMBAI**

(DATTATRAY LOKHANDE)

Inspector

Stamp:

